Material Safety Data Sheet

Chemical Specialties, Inc.

PO Box 27095 Overland Park, KS 66225-7095 NFPA HAZARD RATING 4-EXTREME 3-HIGH 2-MODERATE 1-SLIGHT 0-INSIGNIFICANT

HEALTH FIRE REACTIVITY **SPECIAL**

1 0 0

| Date: Revised July 1, 1993 I. General Information | | | | | | | |
|--|-------------|-------------------------------------|--|----------|-------------------------|-----------|--|
| Product type Rinse Additive | | | Trade Name RINSE 50 | | | | |
| Chemical Family: Inorganic salt | | | Formula: Aluminum hydroxychloride in water | | | | |
| Manufacturer Chemical Specialties, Inc. | | | base. | | | | |
| Manufacture's Address: PO Box 27095 | | | fg's Phone# | | Chemtrec's Phone # | | |
| Overland Park, KS 6225-7095 | | | 3-868-9662 | | 1-800-424-9300 | | |
| Proper DOT Shipping Name : Compound cleanin | | | | | DOT Hazard Class N/A | | |
| II. Hazardous Compounds | | | | | | | |
| Hazardous Components | CAS | # Percent Exposure Limits (PEL/TLV) | | | | | |
| N/A | | | | | ŕ | | |
| | | | | | | | |
| | | | | | | | |
| | | | | <u> </u> | | | |
| | | | | <u> </u> | | | |
| | | | | | | | |
| | | | | | | | |
| III. Physical Data | | | | | | | |
| Boiling Point About the same as water. | | | Specific Gravity 1.320 | | | | |
| Solubility in Water Complete | | | Percent Volatile (wt.) 50 | | | | |
| pH N/A Apperance Clear to slightly hazy liquid | | | Evaporation Rate Slower that water | | | | |
| Apperance Clear to slightly hazy liquid VOC's (% wt.) N/A | | | Odor Negligible odos | | | | |
| IV/A | | | | | | | |
| IV. Fire & Explosive Hazard Data Flash Point (F) N/A | | | | | | | |
| Auto Ignition Temperatus N/A | | | | | | | |
| Auto Ignition Lemperatue N/A Flammable Limits: LEL N/A UEL N/A Extinguishing Media N/A | | | | | | | |
| Special Fire & Fighting Procedures: May | / decompo | se to h | vdrogen chlo | ride s | o wear colf | contained | |
| Special Fire & Fighting Procedures: May decompose to hydrogen chloride, so wear self-contained breathing apparatus if fumes are present. | | | | | | | |
| Unusal Fire & Explosion Hazards: May build up pressure and rupture a sealed container. | | | | | | | |
| , as a summary | | | | | | | |
| i | | | | | | | |
| | | | | | | | |

| V. Health Hazard Data | Kinse | | | | | | |
|--|--------|--|--|--|--|--|--|
| OCHA (DEL) | | | | | | | |
| Listed as carcinogen (known or notantial) NTD. | | | | | | | |
| Symptoms of Exposure: May irritate skin and eyes. | lo | | | | | | |
| inay initate skill allu eyes. | | | | | | | |
| Medical Conditions Aggravated by Exposure: N/A | | | | | | | |
| Primary Route(s) of Entry: | | | | | | | |
| Skin Contact X Eye Contact X Ingestion X Inhalation Absorption | ,, | | | | | | |
| Emergency First Aid: | 41 | | | | | | |
| For skin – rinse skin with water. | | | | | | | |
| For eyes – rinse with water for 15 minutes and get medical attention. | | | | | | | |
| For ingestion – Do not induce vomiting. Get medical attention | | | | | | | |
| VI. Reactivity Data | | | | | | | |
| Stability: Stable X Unstable | | | | | | | |
| Conditions to Avoid: | | | | | | | |
| Incompatability: Materials to Avoid May slowly corrode iron, brass, copper, aluminum & mild | steel. | | | | | | |
| | | | | | | | |
| Hazardous Polymeriztion: May occur Will not occur X | | | | | | | |
| Hazardous Decomposition Products: None known | | | | | | | |
| VII. Environmental Protection Procedures | | | | | | | |
| Spill Response: Wipe up, rinse with water or use floor absorbent. | | | | | | | |
| | | | | | | | |
| Waste Disposal Method: Check federal, state and local regulations. | | | | | | | |
| VIII. Special Protection Information | | | | | | | |
| Eye Protection: Goggles or safety glasses Skin Protection: N/A | | | | | | | |
| Respiratory Protection: Not necessary Ventilation Recommen | ıded: | | | | | | |
| fans | | | | | | | |
| Other Protection: N/A | - | | | | | | |
| IX. Special Precautions | | | | | | | |
| Hygenic Practices in Handling and Storage: Avoid eye and extended skin contact. Store at | I.S., | | | | | | |
| Moderate temperatures. | | | | | | | |
| Precautions for Repair & Maintenance of Contaminated Equipment: Consult Sections V & V!II | to | | | | | | |
| insure safe precedures. | | | | | | | |
| Other Precautions: Keep from freezing. | | | | | | | |
| | | | | | | | |
| The information and recommendations contained herein are based upon data believed to be correct. However, no warranty or guarantee of any kind, expressed or implied, is made and all liability is disclaimed from religious | | | | | | | |